
Data Sheet



Measures



A = 211.30	D1 = 65.0	15 = 222.0	P1	= 4.5	V = 62
B = 50	d3 = 120	M = 163.0	Q	= M12x19	V1 = 50
B1 = 11	G = 278	N = 140	R	= 180	
B2 = 12.8	G1 = 105.5	N1 = 115	S	= 215	
B3 = 4	H = 479.0	N2 = 95	Т	= 250	
B4 = 50	H1 = 144.0	N4 = M8x19	Tightening torque Nm adapter bushin	g = 6.0	
C = 20	L = 339.5	O = 22	Tightening torque Nm shrink disc	= 12.0	
D = 93.5	L1 = 273	P = 8.5	U	= 91.0	