
Data Sheet



Article number:6160401615025Description:Taper bush 1615 bore ø25 mm

Measures



| Bore = 25 Bush type = 1615 D1 = 57 S = 38,1 Screw size = $3/8 \times 5/8"$ t = 28.3 Transmission moment = 486 | b | = 8 |
|---|---------------------|--------------|
| D1 = 57 S = $38,1$ Screw size = $3/8 \times 5/8$ " t = 28.3 | Bore | = 25 |
| S = $38,1$ Screw size = $3/8 \times 5/8$ " t = 28.3 | Bush type | = 1615 |
| Screw size $= 3/8 \times 5/8"$ t $= 28.3$ | D1 | = 57 |
| t = 28.3 | S | = 38,1 |
| | Screw size | = 3/8 x 5/8" |
| Transmission moment = 486 | t | = 28.3 |
| | Transmission moment | = 486 |