
Data Sheet



Measures



A = 112.50	D1 = 35.0	l5 = 159.5	P1	= 3.0	V :
B = 25	d3 = 77	M = 100.5	Q	= M8x12	V1 :
B1 = 19	G = 140	N = 200	R	= 80	
B2 = 21.8	G1 = 51.0	N1 = 165	S	= 100	
B3 = 6	H = 251.0	N2 = 130	Т	= 120	
B4 = 25	H1 = 84.0	N4 = M10x20	Tightening torque Nm adapter bushin	g = 6.0	
C = 20	L = 205.0	O = 11	Tightening torque Nm shrink disc	= 7.0	
D = 47.5	L1 = 170	P = 4.5	U	= 83.0	