
Data Sheet



Measures



A = 128.75	D1 = 43.5	l5 = 197.5	P1	= 3.5	V
B = 32	d3 = 83	M = 135.5	Q	= M10x14	V1 :
B1 = 28	G = 162	N = 250	R	= 110	
B2 = 31.3	G1 = 58.0	N1 = 215	S	= 130	
B3 = 8	H = 290.5	N2 = 180	Т	= 150	
B4 = 32	H1 = 93.5	N4 = M12x16	Tightening torque Nm adapter bushin	g = 6.0	
C = 20	L = 242.5	O = 13	Tightening torque Nm shrink disc	= 7.0	
D = 57.0	L1 = 188	P = 6.0	U	= 120.5	