
Data Sheet



Measures



A = 125.00	D1 = 40.0	l5 = 182.0	P1	= 3.0	V :
B = 30	d3 = 83	M = 120.0	Q	= M8x15	V1:
B1 = 19	G = 160	N = 200	R	= 95	
B2 = 21.8	G1 = 58.0	N1 = 165	S	= 115	
B3 = 6	H = 286.0	N2 = 130	Т	= 140	
B4 = 30	H1 = 92.5	N4 = M10x20	Tightening torque Nm adapter bushin	g = 6.0	
C = 20	L = 217.0	O = 11	Tightening torque Nm shrink disc	= 7.0	
D = 57.0	L1 = 188	P = 5.0	U	= 104.5	