
Data Sheet



712000 200,1 1 7 10

Measures



A = 128.75	D1 = 43.5	I5 = 197.5	P1	= 3.5	V1 = 40
B = 31	d3 = 83	M = 135.5	Q	= M10x14	
B1 = 14	G = 162	N = 160	R	= 110	
B2 = 16.3	G1 = 58.0	N1 = 130	S	= 130	
B3 = 5	H = 290.5	N2 = 110	Т	= 150	
B4 = 32	H1 = 93.5	N4 = M8x16	Tightening torque N m = 14.5		
C = 20	L = 213.0	O = 13	U	= 96.0	
D = 57.0	L1 = 188	P = 6.0	V	= 38	