
Data Sheet



Measures



A = 150.50	D1 = 54.0	I5 = 180.0	P1	= 3.5	V =
B = 36	d3 = 90	M = 125.0	Q	= M10x17	V1 =
B1 = 14	G = 170	N = 160	R	= 110	
B2 = 16.3	G1 = 84.0	N1 = 130	S	= 130	
B3 = 5	H = 326.0	N2 = 110	Т	= 150	
B4 = 35	H1 = 102.0	N4 = M8x16	Tightening torque Nm adapter bushin	g = 6.0	
C = 20	L = 225.5	O = 13	Tightening torque Nm shrink disc	= 8.0	
D = 68.0	L1 = 210	P = 6.5	U	= 95.5	