
Data Sheet



Measures



D1 = 56.5	l5 = 200.0	P1	= 3.5	V =
d3 = 100	M = 144.0	Q	= M12x19	V1 =
G = 218	N = 200	R	= 130	
G1 = 97.5	N1 = 165	S	= 165	
H = 389.0	N2 = 130	Т	= 200	
H1 = 116.0	N4 = M10x20	Tightening torque Nm adapter bushing = 6.0		
L = 265.5	O = 14	Tightening torque Nm shrink disc	= 10.0	
L1 = 242	P = 7.5	U	= 82.0	
	d3 = 100 G = 218 G1 = 97.5 H = 389.0 H1 = 116.0 L = 265.5	d3 = 100	$\begin{array}{llllllllllllllllllllllllllllllllllll$	$\begin{array}{llllllllllllllllllllllllllllllllllll$