
Data Sheet



Measures



A = 211.30	D1 = 65.0	l5 = 222.0	P1	= 4.5	V = 62
B = 50	d3 = 120	M = 163.0	Q	= M12x19	V1 = 50
B1 = 38	G = 278	N = 300	R	= 180	
B2 = 41.3	G1 = 105.5	N1 = 265	S	= 215	
B3 = 10	H = 479.0	N2 = 230	Т	= 250	
B4 = 50	H1 = 144.0	N4 = 14	Tightening torque Nm adapter bushing	g = 6.0	
C = 20	L = 334.0	O = 22	Tightening torque Nm shrink disc	= 12.0	
D = 93.5	L1 = 273	P = 8.5	U	= 91.0	