
Data Sheet



Measures



A = 211.30	D1 = 65.0	l5 = 222.0	P1	= 4.5	V = 62
B = 55	d3 = 120	M = 163.0	Q	= M12x19	V1 = 50
B1 = 14	G = 278	N = 160	R	= 180	
B2 = 16.3	G1 = 105.5	N1 = 130	S	= 215	
B3 = 5	H = 479.0	N2 = 110	Т	= 250	
B4 = 55	H1 = 144.0	N4 = M8x16	Tightening torque Nm adapter bushir	ng = 6.0	
C = 20	L = 339.5	O = 22	Tightening torque Nm shrink disc	= 12.0	
D = 93.5	L1 = 273	P = 8.5	U	= 91.0	