
Data Sheet



Article number: 501004002

Description: Self-aligning bearing FMA 40

Measures



A max	= 40.064	C min	= 79.74599999999995	JB
A min	= 40.02499999999999	Concentric mm = 0.0254		Ret ring
B2 max	= 61.96099999999999	For o-ring	$= 56 \times 3,5$	Static Ic
B2 min	= 61.935000000000002	Н	= 56	Surface
B max	= 62	HA	= 2.2000000000000002	
B min	= 61.97	НВ	= 59	
Bush weight kg = 0.356		J	= 20	
C max	= 80	JA	= 4.099999999999996	

JB
Ret ring part no (DII
Static load (kg)
Surface area kcm